



Product: SiS191/SiS190 1000/100/10 Ethernet MAC controller

Date: 06/08/2005

Document Type: Release Note

Package Version: 1.04

SiS191/SiS190 integrated 1000/100/10 Ethernet Driver Package [V1.04]

1. Windows 2000 driver and Windows XP drivers certified by WHQL as for HCT 12.0 compliant logo drivers.
2. Windows Server 2003 Standard Edition driver certified by WHQL as for HCT 11.2 compliant logo driver.
3. Windows XP Professional x64 Edition and Windows Server 2003 Standard x64 Edition certified by WHQL as for HCT 12.1 compliant logo driver.
4. Submission ID: 984465
5. Supports SiS South Bridge SiS965(191)/SiS965L(190)/SiS966(191)/SiS966L(190).

6. Update Diagnostics Package to v2.16.

7. Add Interrupt Auto-Tune item in registry.

8. Driver Version

[Windows XP Driver]

<u>Filename</u>	<u>Date</u>	<u>Driver Version</u>
SiSGbeXP.sys	05/24/2005	2.0.1039.1040

- Set burst enabled as default.
- Set dynamic compensation.
- Fix the issue of Jumbo Frame.

[Windows 2000 Driver]

<u>Filename</u>	<u>Date</u>	<u>Driver Version</u>
SiSGbe2K.sys	05/24/2005	2.0.1039.1040

- Set burst enabled as default.
- Set dynamic compensation.
- Fix the issue of Jumbo Frame.
- Enhance power saving function.

[Windows Server 2003 Standard Edition Driver]

<u>Filename</u>	<u>Date</u>	<u>Driver Version</u>
SiSGbeXP.sys	05/24/2005	2.0.1039.1040

- Set burst enabled as default.
- Set dynamic compensation.
- Fix the issue of Jumbo Frame.
- Enhance power saving function.



[Windows XP Professional x64 and Windows Server 2003 Standard x64 Edition Driver]

<u>Filename</u>	<u>Date</u>	<u>Driver Version</u>
SiSG564.sys	05/24/2005	2.1.1039.1040

- Set burst enabled as default.
- Set dynamic compensation.
- Fix the issue of Jumbo Frame.
- Enhance power saving function.